

**GOVERNMENT OF ANDHRA PRADESH
ROADS AND BUILDINGS DEPARTMENT**

From:
Sri C.Viswanatha Reddy, M.Tech.,
Executive Engineer,
(R&B) Division,
Guntur.

To:
The Principal,
Dr. K.L.P Public School,
J.K.C College Road,
Ring Road,
Guntur.

Letter No. Soundness Certificate / A8 / GNT / 2025, Dated : 24.03.2025

Sub :-(R&B) Division, Guntur – Structural Soundness Certificates – “Dr.K.L.P.Public School, JKC College Road, Ring Road, Guntur- Issue-Regarding.

Ref :- 1) Representation received by Dr K.L.P Public School, Guntur Dated:-17.03.2025.


* * * * *


With reference to the above, I have personally inspected the “ **Dr Kondabolu Lakshmi Prasad Public School (Senior Secondary)**”, on 24.03.2025 which was located in JKC College Road, Ring Road,, Guntur The existing building RCC framed structures (G+3) Constructed in the year 1983 is utilizing for class.

It is observed that the doors, windows and toilets are in good condition on visual observation, it is observed that the above building is **Structurally sound as on 24.03.2025 to 23.03.2026 one year.**

Encl:- **Soundness Certificate**

Yours faithfully,



Executive Engineer
(R&B) Division, Guntur



24/3/25

SOUNDNESS CERTIFICATE

This is to certify that I have personally inspected the " **Dr Kondabolu Lakshmi Prasad Public School (Senior Secondary)**" on 20.03.2025 which was located in JKC College Road, Ring Road,, Guntur The existing building RCC framed structures (G+3) Constructed in the year 1983 is utilizing for class.

It is observed that the doors, windows and toilets are in good condition On visual observation, it is observed that the above building is **Structurally sound as on 24.03.2025 to 23.03.2026 one year.**


Executive Engineer
(R&B) Division, Guntur


24/3/25